


MICROMASTER 420

Circuit diagrams

General circuit diagram



For an additional digital input (DIN4) external connections should be made:

